

Student Center Project



Exterior Wall Framing and Sheathing Continue

Overhead Plumbing rough in

Renovation: HVAC unit is being hooked up

Current Activities:

- Exterior Wall Framing continues
- Exterior Sheathing continues
- Wall layout continues
- Overhead plumbing started
- Fire Sprinkler continues
- Gym & Student Common space build back continues
- HVAC Unit to be hooked up

Upcoming Activities:

- Exterior metal stud framing to continue
- Roofing to start
- Exterior vapor barrier to start
- Interior ductwork to be installed
- HVAC Unit to be hooked ups continue
- Gym & Student Common space build back continues
- North Portico work will start