

Student Center Project



Exterior Wall Framing and Sheathing Continue



Overhead Fire Protection rough in & Wall layout at offices



Renovation: Gym Duct work and New Addition Supply Duct work

Current Activities:

- Exterior Wall Framing Completing
- Exterior Sheathing continues
- Wall layout Completes
- Overhead plumbing Continues
- Fire Sprinkler continues
- Gym & Student Common space build back continues
- HVAC Unit Continues to be hooked up
- Roof Blocking has started

Upcoming Activities:

- Exterior metal stud framing Completes
- Roof Blocking to continue
- Roofing to start
- Exterior vapor barrier to start
- Interior ductwork continues
- HVAC Unit to be hooked ups continue
- Gym & Student Common space build back continues
- North Portico work to start