

Student Center Project



North Portico Layout and Grading



EIFS & Window Installation



Sheetrock Installation

Current Activities:

- Overhead plumbing, electrical and mechanical continues
- Gym & Student Common space build back continues
- HVAC Unit Continues to be hooked up
- Sheetrock continues
- Roofing Continues
- Metal Roofing started
- EIFS continues
- Cast stone / Masonry continues
- Window installation started
- North Portico - utility work completed
- North Portico – site grading has started

Upcoming Activities:

- Roofing to complete
- Plumbing, Electrical & Mechanical continues
- HVAC Unit hooked ups continue
- Gym & Student Common space build back continues
- Sheetrock install continues
- Mud and tape to continue
- Cast Stone / Masonry to continue
- Window installation to continue
- North Portico – site work continues
- In wall inspections