

Student Center Project



North Portico Grading Continues



Metal Roof is almost complete



Electrical panel boxes and wall rough in



Current Activities:

- Overhead plumbing, electrical and mechanical continues
- Gym & Student Common space build back continues
- HVAC Unit Continues to be hooked up
- Sheetrock continues
- Roofing continues
- Metal Roofing continues
- EIFS continues
- Cast stone / Masonry continues
- Window installation continues
- North Portico – site grading has started

Upcoming Activities:

- Roofing Expansion joint to start
- Plumbing, Electrical & Mechanical continues
- HVAC Unit hooked ups continue
- Gym & Student Common space build back continues
- Sheetrock install continues
- Mud and tape to continue
- Cast Stone / Masonry to continue
- Window installation to continue
- North Portico – site work continues
- In wall inspections